

# PW127M For Sale

ESN: EB0273

Overhauled

## Engine Information

### Turbomachinery Module

TSN: 10,769 CSN: 9,838  
TSO: 0 TSHSI: 0

### Reduction Gear Box

TSN: 10,769 CSN: 9,838 TSO: 0

### Life Limited Parts Values

	TSN	CSN	TR	CR	% Time Remaining
L.P. Impeller	7 313	6 543	7 687	8 457	51%
H.P. Impeller	6 219	7 302	8 781	7 698	59%
H.P. Front Cover	2 882	2 706	12 118	12 294	81%
Seal, Air Interstage	2 882	2 828	12 118	12 172	81%
H.P. Rear Cover	7 472	7 528	7 528	7 472	50%
H.P. Blades	7 302	7 698	7 698	7 302	51%
H.P. Disk	-	-	15 000	15 000	100%
L.P. Disk	-	-	15 000	15 000	100%
1st P.T. Disk	10 769	9 838	19 231	20 162	64%
2nd P.T. Disk	10 769	9 838	19 231	20 162	64%

Limiter: H.P. Rear Cover 7,472 CR  
H.P. Rear Cover 7,528 TR

Enquiries: warrick.h@cla.aero +44 (0) 7368 175 986

# PW127M For Sale

**ESN: EB0273**

Overhauled

## NOTES:

- Availability: 35 Days after Purchase Order and Deposit Receipt
- Released by P&WC, Plant 5, Canada
- Location: North America
- PW127M- BS 1237
- Warranty: 1 Year or 1,000 Operating Hours, whichever Occurs first
- All AD's applicable at release date applied
- Phase 5 Nozzles/ Post SB21891 & SB21905
- Chip Detector Post SB21294 & SB21363
- EEC Pre SB21796, Equivalent to Post SB21904
- AFU Post SB21892
- Fuel Pump Post SB21808
- MFCU SB21835 Not Applicable to P/n: 3244871-6
- IBV SB21718 Not Applicable to P/n: 01R3119957-03
- IBV Post SB21811
- No PMA's used or DER Repairs done
- No Repeat Inspections or Deferred Repairs
- Oil- BP Turbo Oil 2380
- P&WC Letter as per P&WC SIL GEN-135 confirming Engine Service Policy has been re-instated; Warranty has been re-instated, and that the Engine can be returned to service after Incident/ Accident.
- Not in QEC configuration
- LLP Data may change at final assembly

*Data correct as at 16<sup>th</sup> May 2022 and subject to change*

Enquiries: [warrick.h@cla.aero](mailto:warrick.h@cla.aero) +44 (0) 7368 175 986



**C&L Aerospace**