

PW127M For Sale

ESN: EB0094

Overhauled

Engine Information

Turbomachinery Module

TSN:	12,563	CSN:	14,839
TSO:	0	TSHSI:	0

Reduction Gear Box

TSN:	11,952	CSN:	14,035	TSO:	0
------	--------	------	--------	------	---

Life Limited Parts Values

	TSN	CSN	Time Remaining
L.P. Impeller	3,923	3,749	11,077
H.P. Impeller	2,298	2,862	12,702
H.P. Front Cover (1.15)	2,298	3,291	12,702
Seal, Air Interstage (1.25)	2,298	3,578	12,702
H.P. Rear Cover	2,298	2,862	12,702
H.P. Blades	2,298	2,862	12,702
H.P. Disk	2,298	2,862	12,702
L.P. Disk	2,298	2,862	12,702
1st P.T. Disk	12,563	14,839	17,437
2nd P.T. Disk	12,563	14,839	17,437

Limiters:	Seal, Air Interstage	9,137 CR
	L.P. Impeller	11,077 TR

Enquiries: warrick.h@cla.aero +44 (0) 7368 175 986



C&L Aerospace

PW127M For Sale

ESN: EB0094

Overhauled

NOTES:

- Availability: 35 Days after Purchase Order and Deposit Receipt
- Released by P&WC, Plant 5, Canada
- Location: North America
- PW127M- BS 1237
- Warranty: 1 Year or 1,000 Operating Hours, whichever Occurs first
- All AD's applicable at release date applied
- Phase 5 Nozzles/ Post SB21891 & SB21905
- Chip Detector Post SB21294 & SB21363
- EEC Pre SB21796, Equivalent to Post SB21904
- AFU Post SB21892
- Fuel Pump Post SB21808
- No PMA's used or DER Repairs done
- No Repeat Inspections or Deferred Repairs
- Oil- BP Turbo Oil 2380
- P&WC Letter as per P&WC SIL GEN-135 confirming Engine Service Policy has been re-instated; Warranty has been re-instated, and that the Engine can be returned to service after Incident/ Accident.
- Not in QEC configuration

Enquiries: warrick.h@cla.aero +44 (0) 7368 175 986



C&L Aerospace