

**No. 2902**

## **UNS-1C FMS and UNS-1C+ FMS Product Support**

**To: Operators of the UNS-1C and UNS-1C+ FMSs**

**Subject: Discontinuation of Repair Service**

### **Application**

This Service Letter applies to FMS Part Numbers (P/N) 1017-XX-XXX and 10172-XX-XXX

### **Description**

Due to parts obsolescence for the LCD display, CPU board, GPS board and GPS sensor, repair support, will be limited beginning December 2020. Universal Avionics will continue to support repairs not related to these CCAs and will continue to support repairs related to these CCAs while stock is available.

Universal Avionics recommends affected aircraft operators contact their avionics modification provider of choice to explore options for replacing the functionality of FMS P/Ns 1017-XX-XXX and 10172-XX-XXX.

### **Contact Information**

For questions or general information concerning this notice, please contact Customer Support:

Address: Customer Support  
Universal Avionics  
3260 E. Universal Way  
Tucson, AZ 85756-5097  
Ph: +1 520 573 7627  
Ph: 1 800 595 5906  
Fax: +1 520 295 2384  
Email: [customersupport@uasc.com](mailto:customersupport@uasc.com)