

No. 2903

UNS-1D FMS and UNS-1D+ FMS Product Support

To: Operators of the UNS-1D and UNS-1D+ FMSs

Subject: Discontinuation of Repair Service

Application

This Service Letter applies to FMS Part Numbers (P/N) 1192-XX-XXXXXX and 11922-XX-XXXXXX

Description

Due to parts obsolescence for the CPU board, GPS board and GPS sensor, repair support will be limited beginning December 2020. Universal Avionics will continue to support repairs not related to these CCAs and will continue to support repairs related to these CCAs while stock is available.

Universal Avionics recommends affected aircraft operators contact their avionics modification provider of choice to explore options for replacing the functionality of FMS P/Ns 1192-XX-XXXXXX and 11922-XX-XXXXXX.

Contact Information

For questions or general information concerning this notice, please contact Customer Support:

Address: Customer Support
Universal Avionics
3260 E. Universal Way
Tucson, AZ 85756-5097
Ph: +1 520 573 7627
Ph: 1 800 595 5906
Fax: +1 520 295 2384
Email: customersupport@uasc.com