


1. Approving Civil Aviation Authority / Country Transport Canada		2. AUTHORIZED RELEASE CERTIFICATE Form One			3. Form Tracking No. W106406	
4. Organization Name and Address  Aviatechnik Corporation 710 Gana Court Mississauga, ON, Canada, L5S 1P2		Tel: 905-890-7778 www.aviatechnikcorp.com		5. Work Order / Contract / Invoice R657935		
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial / Batch No.	11. Status / Work	
1	Locking Stay, MLG	190-70250-409	1	00469	Repaired	
12. Remarks: * Repaired in accordance with CMM # 32-11-08, Rev # 9 dated 30 June 2018. * Full details of work performed in work order W106406. * For the replacement parts refer to Teardown Report. * Landing Gear Log Card attached. * CSN-20194, CSO-3861. * Overhauled on 24 January 2017.						
13a. Certifies that the items identified above were manufactured in conformity to: ☐ Approved design data and are in condition for safe operation. ☐ Non approved design data specified in block 12.		14a. ☒ CAR 571.10 Maintenance Release. ☐ Other regulations specified in block 12. Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, has been performed in compliance with the Canadian Aviation Regulations.				
13b. Signature	13c. Approved Organization Number	14b. Signature		14c. Approved Organization Number		
				50-12		
13d. Name	13e. Date (dd/mm/yyyy)	14d. Name		14e. Date (dd/mm/yyyy)		
		Alexey Baydala		01/Nov/2024		
(Previously form 24-0078)						
Installer Responsibilities This certificate does not constitute authority to install. Installer working in accordance with the national regulations of a country other than that specified in block 1, must ensure that their regulations recognize certifications from the country specified. Statements in blocks 13a and 14a do not constitute installation certification. In all cases, the technical record must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.						



LANDING GEAR LOG CARD

AUTHORIZED OVERHAUL LIFE: 25000 cvc/12 years

SERIAL NO: 00469

AIRCRAFT INSTALLATION RECORDS

[illegible]

PRIMARY MEMBER RECORDS

[illegible]

4. View ultimate lives and/or inspection requirements refer to Aircraft Airworthiness Data and to the appropriate Liebherr and Embraer S.A. Service Bulletin.

2. It is the Operator's responsibility to ensure these records are fully and accurately maintained.
3. Lives of primary members shall be maintained. Failure to comply may result in premature scrap.
4. Should a primary member be removed from the unit it must be suitably tagged to indicate consumed life.
5. If the Part No. is changed a new Log Card must be completed, transferring relevant information from the previous Card.
6. The Log Card was created refer to client's provided documents.

		Bangor (Main Office) 40 Wyoming Ave Bangor, ME 04401 Tel: +1 207 217 0090 Fax: +1 207 945 0992	Australia ABA 14 949 098 590 5/37 Wendorah St Stafford QLD 4053 Tel: +61 3354 8100 Fax: +61 3353 8111	United Kingdom Headcorn Road Sutton Valence, ME17 3EL Great Britain Tel: +44 (0) 1622 960 117	Repair Order Order #: R657935 Account Number: Date Printed: 29 Aug 2024 Time: 9:51:28 AM No. of Items: 1 Page: 1		
C&L Aerospace		www.cla.aero		Contact: Robert Howard Email: Repairs@CLA.Aero			
To: ATTN: NATALIYA NECHYPORENKO AVIATECHNIK CORPORATION 710 GANA COURT MISSISSAUGA, ON L5S1P2 Canada PHONE: 905 890 7778				Ship To: C & L AEROSPACE 40 WYOMING AVE BANGOR, ME 04401 USA			
Ship Via: TBA Ship Via Acc: Terms: NET 30				RO Date: 5/14/2024 Warranty: No			
<i>All items subject to our inspection and acceptance</i>							
Item	Part Number/Description	CD	Qty	UOM	Serial	Return Date	Line Amt
1	190-70250-409 MLG LOCKING STAY SO #: Parts: \$.00 Labor: \$1,500.00 Misc: \$.00 Instructions: PLEASE INSPECT AND QUOTE TO TEST/INSPECT/RECERTIFY *PLEASE PROVIDE QUOTE WITHIN TWO WEEKS AFTER PART ARRIVES TO SHOP *PLEASE PROVIDE ONE QUOTE UTILIZING ALL NEW PARTS, AND A SECOND QUOTE PROVIDING AS MANY PMA, EPA AND SERVICABLE PARTS AS POSSIBLE *INDIVIDUAL PARTS LIST AND PRICING WITH QUOTE IS REQUIRED. **TRIPLE RELEASE (FAA, EASA, TCCA) CERTIFICATION REQUIRED(SEPARATE 8130, FORM ONE, AND TCCA CERTS TOGETHER ARE ALSO ACCEPTABLE.) *PLEASE ALSO INCLUDE CAA FORM 1 AS SEPERATE CERTIFICATION * ORIGINAL TEARDOWN REPORT REQUIRED. * DER REPAIRS OR DAR MUST BE DISCLOSED AT	AR	1.00	EA	00469	25 Oct 2024	\$1,500.00
						See last page for totals	
Authorized Signature: Robert Howard							
Standard Terms & Conditions:							
1. Please ensure that the Repair Order is read carefully as failure to comply with the requirements will result in the Supplier being responsible for any charges incurred for the return of the goods to the Suppliers premises. 2. All goods purchased through this Repair Order are subject to a quality inspection to be carried out by C&L Aerospace 3. C&L Aerospace reserves the right to return any goods that do not meet the requirements of the purchase order or are faulty in any way up to 30 days after receipt of consignment. 4. This repair order is only valid when accompanied by an authorised signature. 5. For Exchange transactions, the Seller agrees to, when applicable: * A part known to have been subjected to conditions of extreme stress, heat, or environment are so identified. * All Airworthiness Directives (AD's) that are represented as having been accomplished are documented. * Items identified as OH, Repaired, Inspected, or Modified have the appropriate signed and dated documentation attached							

 C&L Aerospace	Bangor (Main Office) 40 Wyoming Ave Bangor, ME 04401 Tel: +1 207 217 8050 Fax: +1 207 845 0992	Australia ABN 14 949 088 590 1/37 Wandorah St Stafford QLD 4053 Tel: +61 3354 8100 Fax: +61 3353 6111	United Kingdom Healden Road Sutton Valence, ME17 3EL Great Britain Tel: +44 (0) 1622 960 117	Repair Order Order #: R657935 Account Number: Date Printed: 29 Aug 2024 Time: 9:51:29 AM No. of Items: 1 Page: 2			
	Contact: Robert Howard Email: Repairs@CLA.Aero						
To: ATTN: NATALIYA NECHYPORENKO AVIATECHNIK CORPORATION 710 GANA COURT MISSISSAUGA, ON L5S1P2 Canada PHONE: 905 890 7778			Ship To: C & L AEROSPACE 40 WYOMING AVE BANGOR, ME 04401 USA				
Ship Via: TBA Ship Via Acc: Terms: NET 30			RO Date: 5/14/2024 Warranty: No				
<i>All items subject to our inspection and acceptance</i>							
Item	Part Number/Description	CD	Qty	UOM	Serial	Return Date	Line Amt
	THE TIME OF QUOTING. * MANUAL REFERENCE & REVISION # MUST BE REFERENCED IN CERTIFICATION. * CURRENT REVISION OF THE APPLICABLE CMM MUST BE USED UNLESS OTHERWISE APPROVED BY C&L AEROSPACE AND ANY COSTS TO BRING A UNIT IN LINE WITH THE CURRENT REV. AFTER RELEASE WILL BE FOR THE SHOP, INCLUDING, AND NOT LIMITED TO FREIGHT, PARTS AND LABOR. * SHIPPER RESPONSIBLE FOR DAMAGE TO POORLY PACKAGED ITEMS. * SHIPPER RESPONSIBLE FOR PROPER CUSTOMS PAPERWORK FOR INTERNATIONAL SHIPMENTS. * WORK PERFORMED MUST BE DONE IAW CURRENT OEM TECH DATA OR FAA APPROVED DATA. * PART NUMBER MUST BE IDENTIFIED ON PART IF NOT VISIBLE. * SERIAL NUMBER MUST BE IDENTIFIED ON PART IF NOT VISIBLE AND ASSIGNED IF PART DOES NOT ALREADY HAVE A S/N. * PLEASE DO NOT INCLUDE ANY INVOICES OR PAPERWORK THAT INCLUDES PRICING IN THE RETURN SHIPMENT						
						Parts Total:	\$.00
						Labor Total:	\$1,500.00
						Misc Total:	\$.00
						Total:	\$1,500.00
						US Dollars	
Authorized Signature: Robert Howard							
Standard Terms & Conditions: 1. Please ensure that the Repair Order is read carefully as failure to comply with the requirements will result in the Supplier being responsible for any charges incurred for the return of the goods to the Suppliers premises. 2. All goods purchased through this Repair Order are subject to a quality inspection to be carried out by C&L Aerospace 3. C&L Aerospace reserves the right to return any goods that do not meet the requirements of the purchase order or are faulty in any way up to 30 days after receipt of consignment. 4. This repair order is only valid when accompanied by an authorised signature. 5. For Exchange transactions, the Seller agrees to, when applicable: * A part known to have been subjected to conditions of extreme stress, heat, or environment are so identified. * All Airworthiness Directives (AD's) that are represented as having been accomplished are documented. * Items identified as OH, Repaired, Inspected, or Modified have the appropriate signed and dated documentation attached							
Form created with Quantum Control(tm) technology. Product Licensed to: C&L Aerospace							

LIMITED LIABILITY COMPANY

«AIRCOMPANY «IKAR»

Karagandinskaya st. 58/1, building 4, office 9,
Orenburg region, Orenburg, 460036, Russia
Correspondence address:
Karagandinskaya st. 58/1, building 4, office 9,
Orenburg region, Orenburg, 460036, Russia
phone +7 (3532) 48 79 99

Date: 20 September 2022

Landing Gear Status / Statement


To Whom It May Concern:

Aircraft Embraer 190-100LR MSN 19000259 reg. VP-BZJ, has been operated by LLC «Aircompany «IKAR» during the period from 17 August 2018 (TAH 20038,67 and TAC 12382) to 15 September 2022 (TAH 27140:53 and TAC 16241) had below listed Landing Gear assemblies installed:

Description	Type/Part No.	Serial No.	TSN	CSN
Nose Landing Gear	190-70450-403	00146	29076:20	22518
LH Main Landing Gear	4259A0000-02	00350	26310:13	20194
RH Main Landing Gear	4260A0000-02	05345	26273:13	20185

I hereby certify that the above stated Landing Gear Assemblies and all its major components as delivered to LLC «Aircompany «IKAR», and during the period stated above, were not removed and remain fitted to the Airframe MSN: 19000259 at re-delivery.

Authorised Airline Representative

Signature: 
Name: Aleksandr Trushliakov
Position: E190 systems lead engineer
Date: 20-September-2022

LEFT MAIN LANDING GEAR LLP STATUS

MSN: 19000259
Registration: VP-BZJ
TSN: 27140:53
CSN: 16,241

Date: 14-Sep-22

W106406

«AIRCOMPANY «IKAR»
Karagandinskaya st. 58/1, building 4, office 9,
Orenburg region, Orenburg, 460036, Russia
Correspondence address:
Karagandinskaya st. 58/1, building 4, office 9,
Orenburg region, Orenburg, 460036, Russia
phone +7 (3532) 48 79 99

LH MLG DATA	LAST SHOP VISIT	MLG WHEN INSTALLED	NLG CURRENT
INSTALLATION DATE: 03-Apr-17	CSN: 16,333	CSN: 16,333	CSN: 20,194
LH MLG PIN: 4259A0000-02	CSO: 0	CSO: 0	CSO: 3,861
LH MLG SN: 350	DATE: 25/01/2017	TSN: -	CSInstall: 3,861
	TSN: -	A/C FH: -	TSN: -
		A/C FC: 12,380	


LH MLG - Shock Strut Assy	4259A0000-02	350	16,333	3,861	20,194			
NOMENCLATURE	PART NUMBER	SERIAL NUMBER	CYCLES AT INSTALLATION	CSI	CSN CURRENT	LIFE LIMIT	REMAIN	Aircraft CSN at inst
TUBE INNER	2821-0080	HM00363	16,333	3,861	20,194	56000	35,806	12,380
PINTLE PIN FWD	2821-0067	L243	18,756	3,861	22,617	56000	33,383	12,380
PINTLE PIN AFT	2821-0025	L519	16,333	3,861	20,194	56000	35,806	12,380
MAIN FITTING LH	2821-0111	L0637	16,333	3,861	20,194	56000	35,806	12,380
SLIDING TUBE	2821-0221	L0556	16,333	3,861	20,194	56000	35,806	12,380
MLG AXLE	2821-0202	L0477	16,324	3,861	20,185	56000	35,815	12,380
TORQUE LINK UPPER	2821-0310	L0520	16,333	3,861	20,194	56000	35,806	12,380
TORQUE LINK LOWER	2821-0410	L0507	16,333	3,861	20,194	56000	35,806	12,380
BOLT LOWER CARDAN	2821-0622	603	16,333	3,861	20,194	56000	35,806	12,380
SHIMMY DAMPER	2265A0000-03	210	17,459	3,861	21,320	56000	34,680	12,380
BOLT	2821-0082	L182	16,333	3,861	20,194	56000	35,806	12,380
BOLT	1840-0021	L1097	16,333	3,861	20,194	56000	35,806	12,380
BOLT	2821-0001	L409	16,333	3,861	20,194	56000	35,806	12,380

LH MLG - Locking Stay Assy	190-70250-409	00469	16,333	3,861	20,194			
NOMENCLATURE	PART NUMBER	SERIAL NUMBER	CYCLES AT INSTALLATION	CSI	CSN CURRENT	LIFE LIMIT	REMAIN	Aircraft CSN at inst
Stay, Locking Lower	190-70262-007	1479839/002	0	3,861	3,861	56000	52,139	12,380
Stay, Locking Upper	190-70254-005	AP0515	16,333	3,861	20,194	56000	35,806	12,380
Bolt	170-70274-001	1225460/025	16,333	3,861	20,194	56000	35,806	12,380

LH MLG - Side Stay Assy	190-70200-401	00045	16,333	3,861	20,194			
NOMENCLATURE	PART NUMBER	SERIAL NUMBER	CYCLES AT INSTALLATION	CSI	CSN CURRENT	LIFE LIMIT	REMAIN	Aircraft CSN at inst
Stay, Lower	190-70162-003	AP0532	16,333	3,861	20,194	44000	23,806	12,380
Stay, Upper	190-70154-003	AP0538	16,333	3,861	20,194	44000	23,806	12,380
Bolt	190-70156-003	1203078/003	16,333	3,861	20,194	56000	35,806	12,380
CRANK BOLT	190-70164-005	1189844/008	16,333	3,861	20,194	56000	35,806	12,380
SIDE STAY PIVOT BOLT	190-70195-001	1154871/005	0	3,861	3,861	56000	52,139	12,380

Authorised Airline Representative

Signature: _____
Name: Aleksandr Trushilakov
Position: E190 systems lead engineer
Date: 14 Sep 2022



Subject: Non Accident / Incident Statement

Date: May 10th, 2017

To whom it may concern:

Model: ERJ190

Aircraft Serial Number: 259

Aircraft Registration: N982TA

Manufacturer: EMBRAER

Total Time: 20037.40

Total Cycles: 12381

This is to confirm that, the above referenced Aircraft and its associated components were operated by TACA since 30 March 2009 up to re-delivery to Nordic Aviation Capital. During that period of time, the above referenced equipment has not been involved in any accident (according to I. C. A. O. Annex 13 Paragraph B) or serious Incident (according to I. C. A. O. Annex 13 Chapter 1).

This Aircraft has not been involved in any Major failure or fire, extreme stress or neither over-temperature outside of normal operation nor any part fitted was obtained from any government or military source and they were not immersed in salt water during its operation with TACA Group.


Godofredo Ortiz
TACA International Airlines, S. A.
Quality Control Inspector

W106406



NO ACCIDENT/ INCIDENT LETTER

October 5, 2016.

QA-58-2016

To Whom it may Concern;

It is hereby declared to the best of our knowledge, the parts listed below and its sub-Assemblies have not been involved in any serious incident (fire, crash, failure) or accident during its time in service on ERJ-190-100 LR/ SN 19000122 and ERJ-190-100 IGW/ SN 19000174

Description	Part Number Detail	Serial Number	TSN at Removal	CSN at Removal	Installation Date
NLG Shock Strut	190-70453-601	00146	21,974:07	18,657	Sep 10, 2007
NLG Drag Brace	190-70550-403	00208	21,974:07	18,657	Sep 10, 2007
NLG Locking Stay	190-70650-401	00152	21,974:07	18,657	Sep 10, 2007
MLG Shock Strut LH	2821A0000-04	00226	21,974:07	18,657	Sep 10, 2007
MLG Side Stay	190-70150-403	00143	21,974:07	18,657	Sep 10, 2007
MLG Locking Stay	190-70250-409	00304	21,974:07	18,657	Sep 10, 2007
MLG Shock Strut RH	2822A0000-04	05230	21,974:07	18,657	Sep 29, 2007
MLG Side Stay	190-70150-404	00140	21,974:07	18,657	Sep 29, 2007
MLG Locking Stay	190-70250-409	00306	21,974:07	18,657	Sep 29, 2007
Shimmy Damper Assy RH	2265A0000-02	00345	19,814:01	12,362	Dec 04, 2011

Installed original on ERJ-190-100 LR SN 19000122 and removed on September 22, 2015.

Parts were installed on September 22, 2015 and removed on September 20, 2016 from ERJ-190-100 IGW / SN 19000174.

Best Regards

A handwritten signature in dark ink, appearing to read "Virgilio De Mares".

A handwritten signature in dark ink, appearing to read "Virgilio De Mares".

Virgilio De Mares

QA Mx Manager

VP Safety & Quality

Copa Airlines

Cc File

- Final Teardown Report -

HAWKER PACIFIC AEROSPACE FAA Repair Station R3R817L		Hawker Pacific Aerospace 11240 Sherman Way Sun Valley, CA. 91352 USA Tel: (818) 765-6201 Fax: (818) 765-4158	Sales Ord. 660009403 Receipt Date Jul 29, 2016 Customer COMPANIA PANAMENA DE AVIACION/LMS Customer P.O. Y0009517 Urgency Tail # HK4560
---	--	--	---

Receiving Planner Work Order Information				
Qty	P.O. Part Number	Description	Serial Number	Manufacturer
1	190-70250-409	LOCKING STAY, MLG	00469	ELEB - EQUIPAMENTOS LTDA DO BRASIL
Customer Reported Discrepancy			CSO	TSO
N/A			-	-
Warranty	N/A			
Customer Instructions	OVERHAUL			

Initial Test
Initial Evaluation Results HPA RECEIVED MLG LOCKING STAY ASSEMBLY P/N 190-70250-409, S/N 00469 IN FAIR CONDITION. THE FOLLOWING PARTS WERE REPLACED IN ORDER TO IMPROVE THE TURN AROUND TIME (TAT). 1) LOWER STAY ASSEMBLY P/N 190-70260-407, S/N 1234643/001 REMOVED OFF OF COPA HK-4560 AND REPLACED WITH NEW UNIT. SEE ATTACHED LIST FOR PARTS REQUIRING REPAIR CONCESSION(IDR). ALL PARTS WERE RELEASED FOR OVERHAUL, PRESENTED NORMAL WEAR CONDITIONS, AND WERE DETERMINED TO BE DIMENSIONALLY ACCEPTABLE PER OHM LIMITS. UNIT WILL BE OVERHAULED IAW LIEBHERR CMM 32-11-08.

Repair Action Description		Print by:	U554705	Print at:	Jan 18, 2017
Work accomplished OVERHAULED IN ACCORDANCE WITH LIEBHERR CMM CHAPTER 32-11-08 REV 08 DATED 30JUN2015 ACCOMPLISHED EMBRAER SERVICE BULLETIN 190-32-0047. TSO: 0:00 CSO: 0:00 RSL: UNLIMITED SEE ATTACHMENTS FOR NIS, AD/SB STATUS, AND LLP DATA		S/N	00469	Publication	32-11-08
Repair Action Descr. created by U554705 As shipped Part Number 190-70250-409 Signature - Certified Mechanic/Supervisor: <i>Alberto Sarmas</i> Signature - Certified Inspector: <i>[Signature]</i>		Cert #:	3871720	Date:	JAN 24 2017
		Cert #:	3043312	Date:	JAN 24 2017

Approving Civil Aviation
Authority / Country

2.

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, Airworthiness Approval Tag

3. Form Tracking Number:

107212

Organization Name
and Address:

HAWKER PACIFIC
AEROSPACE

Hawker Pacific Aerospace
Repair Station No. RJ3R817L
11240 Sherman Way
Sun Valley, CA, 91352

5. Work Order/Contract/Invoice Number:

660009403 /

Item	7. Description	8. Part Number	9. Quantity	10. Serial Number	11. Status/Work
1	LOCKING STAY, MLG	190-70250-409	1	00469	OVERHAULED

Remarks: Life Details: TSN: 19208:00 CSN: 16333:00

Y0009517

OVERHAULED IN ACCORDANCE WITH LIEBHERR CMM CHAPTER 32-11-08 REV 08 DATED 30JUN2015
ACCOMPLISHED EMBRAER SERVICE BULLETIN 190-32-0047.

TSO: 0:00

CSO: 0:00

RSL: UNLIMITED

SEE ATTACHMENTS FOR NIS, AD/SB STATUS, AND LLP DATA

1a. Certifies the items identified above were manufactured in conformity to:

☐ Approved design data and are in condition for safe operation.

☐ Non-approved design data specified in Block 12.

14a. ☒ 14 CFR 43.9 Return to Service

☐ Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

1b. Authorized Signature:

13c. Approval / Authorization No.:

14b. Authorized Signature:

HPI
34

14c. Approval Certificate No.:

RJ3R817L

13d. Name:

13e. Date:

14d. Name: Patrick Nandet

14e. Date: (dd/mm/yyyy)
24.Jan.2017

USER / INSTALLER RESPONSIBILITIES

Note: 1). It is important to understand that the existence of the document alone does not automatically constitute authority to install the part/component/assembly.

2) Where the user/installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts parts/components/assemblies from the Airworthiness Authority of the country specified in block 1.

3) Statements 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LIFE LIMIT REPORT

**11240 SHERMAN WAY
SUN VALLEY, CA 91352**

HAWKER PACIFIC
AEROSPACE

FAA REPAIR STATION
RJ3R817L
PAGE 1 OF 1

PAGE 1 OF 1

REMOVAL

REMOVAL		HPA WO #:	660009403
V/C #:	HK-4560	CUST PO #:	Y0009517
POS:	LH MLG	CUST P/N:	N/A
DATE:	Aug-16	MFG P/N:	190-70250-40
		MFG S/N:	00469

INSTALL

A/C #:	N/A
ELIGIBILITY:	E190/E195
DATE:	Jan-17

E190 LH LOCKING STAY ASSEMBLY

SAFETY LIFE LIMITS: E190 MRB-1928 REV 10 DATED 28APR2016

AS RECEIVED BY HPA

[illegible]

AS RELEASED BY HPA

[illegible]

ALL LIFE LIMITS HAVE BEEN REVIEWED AND VERIFIED TO APPROVED AND/OR ACCEPTED DATA.
 UMULATIVE CYCLE INFORMATION FOR EACH LIFE LIMITED COMPONENT OR ASSEMBLY
 PROVIDED BY THE CUSTOMER. DOCUMENTATION IS RETAINED ON FILE AT THIS REPAIR FACILITY.

DATE: JAN 23 2017


VERIFIED BY:  DATE: JAN 23 2017

⑥ CONTROLLED COMPONENTS FITTED

CONTROLLED COMPONENTS IDENTIFICATION (AS PER MRB)			LIFE USED AT FITMENT			LIFE USED AT REMOVAL			PROCURABLE ITEMS (AS PER CHM)			SERIAL NUMBER
PART NUMBER	SERIAL NUMBER	DESCRIPTION	DATE	EQUIPMENT CYCLES	COMPONENT CYCLES SINCE NEW	DATE	EQUIPMENT CYCLES	COMPONENT CYCLES SINCE NEW	PART NUMBER	DESCRIPTION		
170-70274-001	1225460/025	BOLT - MLG	JUL/14/08	0	0	-				170-70274-001	BOLT - MLG	1225460
190-70254-005	AP 0515	STAY, LOCKING UPPER - MLG	JUL/14/08	0	0	-				190-70252-407	STAY, UPPER ASSY- MLG	1227924
190-70262-005	AP 0658	STAY, LOCKING LOWER - MLG	JUL/14/08	0	0	-				190-70260-407	STAY, LOWER ASSY- MLG	1234845
190-70260-007	147983/002	STAY, LOCKING LOWER - MLG	MAR/06/17	16,333	0	-	16,333	16,333		190-70260-407	STAY, LOWER ASSY - MLG	14855

IF NECESSARY, ATTACH ADDITIONAL SHEETS.

W106406

1. País (Country) BRASIL		2. AGÊNCIA NACIONAL DE AVIAÇÃO CIVIL (BRAZILIAN CIVIL AVIATION AUTHORITY) CERTIFICADO DE LIBERAÇÃO AUTORIZADA (AUTHORIZED RELEASE CERTIFICATE) ETIQUETA DE APROVAÇÃO DE AERONAVEGABILIDADE (AIRWORTHINESS APPROVAL TAG)				3. Certificado Nº (Certificate No./System Tracking Ref.) ELB 1301001023 Pag. 2 / 2	
4. Empresa (Organization) Embraer - Empresa Brasileira de Aeronáutica S/A COP E-7203-01		Supplier: ELEB EQUIPAMENTOS LTDA R. Itabalana, 40, São José dos Campos - São Paulo, Brasil COP E-2000 07-01				5. Ordem Serviço/Contrato/Nota Fiscal (Work Order/Contract or Invoice) 80107385	
6. Item (Item)	7. Descrição (Description)	8. Número da Peça (Part Number)	9. Aplicabilidade* (Eligibility)	10. Quantidade (Quantity)	11. Número de Série/Lote (Serial/Batch Number)	12. Categoria/Trabalho (Status/Work)	
13. Observações (Remarks) PN190-70260-407 SN1485541/001; PN190-70262-007 SN1482438/003 PN190-70260-407 SN1485549/001; PN190-70262-007 SN1482438/005 PN190-70260-407 SN1485552/001; PN190-70262-007 SN1478939/002.							
Partes com vida limitada devem ser acompanhadas de histórico de manutenção incluindo tempo total/ciclo/tempo, desde que novo. (Limited life parts must be accompanied by maintenance history including total time/cycle/time, since new).							
14. Certifica que o(s) item(ns) acima identificado(s) foi(foram)/fabricado(s) em conformidade com: (Certifies that the article(s) identified above was(were) manufactured in conformity to :) ☒ dados de projeto aprovados e está(ão) em condição segura de operação (approved design data and are in a condition for safe operation) ☐ dados de projeto não aprovado especificado no bloco 13 (non-approved design data specified in block 13)		19. ☐ Retorno ao serviço de acordo com RBHA 43.9. (Return to service in accordance with RBHA 43.9) ☐ Outros regulamentos especificados no bloco 13 (Other regulations specified in block 13)		Certifica que, a menos especificado no bloco 13, o trabalho especificado no bloco 12 e descrito no bloco 13 foi executado de acordo com o regulamento Brasileiro de Homologação Aeronáutica-RBHA43 em relação ao trabalho realizado a(s) peça(s) e(são) aprovada(s) para retorno ao serviço. (Certifies that, unless otherwise specified in block 13, the work identified in block 12 and described in block 13 was accomplished in accordance with Brazilian Regulation for Aeronautical Certification -RBHA 43 and in respect to the work performed the part(s) is(are) approved for return to service.)			
15. Assinatura do Representante da ANAC (Signature ANAC Representative) 		16. Nº Autorização da ANAC (ANAC Authorization No) PCF 2007C03-04		20. Pessoa Autorizada (Authorized Signature) 21. Nº COP/CHETA (Certificate Number)		22. Nome (Name) 23. Data (Date)	
17. Nome (Name) JULIA MARIA COUTINHO DA SILVA		18. Data (Date) JUN/19/2013					

*O INSTALADOR DEVE FAZER VERIFICAÇÃO CRUZADA DA APLICABILIDADE ATRAVÉS DOS DADOS TÉCNICOS APLICÁVEIS. (INSTALLER MUST CROSS CHECK ELIGIBILITY WITH APPLICABLE TECHNICAL DATA)

RESPONSABILIDADE DO USUÁRIO / INSTALLER RESPONSABILITY
(É IMPORTANTE COMPREENDER QUE A EXISTÊNCIA DESTES DOCUMENTOS POR SI SÓ NÃO CONSTITUI AUTOMATICAMENTE UMA AUTORIZAÇÃO PARA INSTALAR A PARTE/COMPONENTE/CONJUNTO. (IT IS IMPORTANT TO UNDERSTAND THAT THE EXISTENCE OF THIS DOCUMENT ALONE DOES NOT AUTOMATICALLY CONSTITUTE AUTHORITY TO INSTALL THE PART / COMPONENT / ASSEMBLY).
SE O TRABALHO DO USUÁRIO/INSTALADOR É REALIZADO DE ACORDO COM OS REGULAMENTOS NACIONAIS DE UMA AUTORIDADE DE AERONAVEGABILIDADE DIFERENTE DA AUTORIDADE DE AERONAVEGABILIDADE DO PAÍS ESPECIFICADO NO BLOCO 1, É ESSENCIAL QUE O USUÁRIO/INSTALADOR ASSEGURE QUE A SUA AUTORIDADE DE AERONAVEGABILIDADE ACEITA PARTES/COMPONENTES/CONJUNTOS DA AUTORIDADE DE AERONAVEGABILIDADE DO PAÍS ESPECIFICADO NO BLOCO 1.)
AS DECLARAÇÕES NOS BLOCOS 14 E 19 NÃO CONSTITUEM UM CERTIFICADO DE INSTALAÇÃO. EM TODOS OS CASOS, OS REGISTROS DE MANUTENÇÃO DA AERONAVE DEVEM CONTER UM CERTIFICADO DE INSTALAÇÃO EMITIDO DE ACORDO COM REGULAMENTOS NACIONAIS PELO USUÁRIO/INSTALADOR ANTES QUE A AERONAVE POSSA SER LIBERADA PARA VOO.
(STATEMENTS IN BLOCK 14 AND 19 DO NOT CONSTITUTE INSTALLATION CERTIFICATION. IN ALL CASES, AIRCRAFT MAINTENANCE RECORDS MUST CONTAIN AN INSTALLATION CERTIFICATION ISSUED IN ACCORDANCE WITH THE NATIONAL REGULATIONS BY THE USER / INSTALLER BEFORE THE AIRCRAFT MAY BE FLOWN).
USER / INSTALLER RESPONSABILITY
(IT IS IMPORTANT TO UNDERSTAND THAT THE EXISTENCE OF THIS DOCUMENT ALONE DOES NOT AUTOMATICALLY CONSTITUTE AUTHORITY TO INSTALL THE PART / COMPONENT / ASSEMBLY).
(WHERE THE USER / INSTALLER WORK IS PERFORMED IN ACCORDANCE WITH THE NATIONAL REGULATIONS OF AN AIRWORTHINESS AUTHORITY DIFFERENT THAN THE AIRWORTHINESS AUTHORITY OF THE COUNTRY SPECIFIED IN BLOCK 1, IT IS ESSENTIAL THAT THE USER/INSTALLER ENSURES THAT HIS/HER AIRWORTHINESS AUTHORITY ACCEPTS PARTS/COMPONENTS/ASSEMBLIES FROM THE AIRWORTHINESS AUTHORITY OF THE COUNTRY SPECIFIED IN BLOCK 1).
(STATEMENTS IN BLOCK 14 AND 19 DO NOT CONSTITUTE INSTALLATION CERTIFICATION. IN ALL CASES, AIRCRAFT MAINTENANCE RECORDS MUST CONTAIN AN INSTALLATION CERTIFICATION ISSUED IN ACCORDANCE WITH THE NATIONAL REGULATIONS BY THE USER / INSTALLER BEFORE THE AIRCRAFT MAY BE FLOWN).

CERTIFIED
TRUE COPY

HPI
204
MFG