



Contact your local Sales Representative
+1 207 217 6050 | sales@cla.aero

ENGINE FOR SALE:

GTCP30-92C S/N P-150

APU recently removed from Hawker 800A S/N: 258034 during aircraft disassembly and repaired by Piedmont. Unit is crated, preserved, and ready to ship.

Engine Details:

Hobbs Meter Reading: 4891.5
Time since repair: 0 Hours
Last repair facility: Piedmont aviation W/O# AN20801
8130-Dual release included
Dated: NOV -15 -2012

APU DUAL RELEASE

Note: This engine is up to the following SB standard:

Accessory Inventory Listing

P/N	
369945-6	Atomizer
394206-5	FCU
370854	EGT
694890-1	Overspeed Switch
693012	Tach Generator
379908	Fuel Solenoid
354972-6	Oil Pressure Regulator
305179-1	Wiring Harness
107996-81-1	Load Stat