



# C&L Aerospace

**Engine Model:** CT7-9B

**Aircraft:** Saab 340B

**PTM S/N:** GE-L-085698

**LSV Date for Refurbishment:** April 4, 2018



**C&L  
AEROSPACE**

**TSN:** 31,459.9

**TSLR:** 0

**CSN:** 33,137

**CSLR:** 0

**LSV Date:** April 4, 2018

## Power Turbine Module S/N GE-L-085698

### INTRODUCTION:

This PTM was input to H+S Aviation for a major work scope and repaired on April 4, 2018.

### LIFE LIMITED COMPONENT DETAILS:

#### POWER TURBINE MODULE:

ITEM	P/N	TSN	CSN	LIFE LIMIT	LIFE REMAINING
Stage 3 Disk	6068T21P02	0.0	0	18600	18600
Stage 4 Disk	6068T32P05	4278.1	5319	18600	13281
Stage 3 Blades	6071T83P02	2728.2	3125	N/A	N/A
Stage 4 Blades	6058T93P01	17168.2	18129	N/A	N/A
TISS	5060T86P05	2728.2	3125	16000	12875
PT Shaft	5121T01G02	2728.2	3125	30000	26875

### SERVICE BULLETINS INCORPORATED:

72-000 R8	72-408 R1	72-480 R1	72-410
75-028	79-027 R1	72-395	72-488
72-489	72-438	72-430	72-454
72-277 R1	72-294	72-343	72-363 R1
72-365	72-368	72-375	72-395

### SUMMARY:

This PTM was repaired by H+S Aviation IAW SEI 578 Rev. 58 on April 4, 2018 where all mandatory AD's were accomplished. The PTM was repaired and released with an EASA Dual Release and the first limiter is the Turbine Interstage Seal with 12,875 cycles remaining. Contact your Regional Sales Manager at C&L Aerospace for more information.

**\*Note:**

The information contained in this document has been provided by C&L Aerospace, LLC and is accurate to the best of their knowledge. C&L Aerospace, LLC is not liable for any errors which may be contained in this document. Parties interested in the products shown in this document are responsible for verifying the accuracy of all subject matter.